

100 year old statue
broken by vandalism
is shipped to our
facility to be welded
back together. This is
the top half.



Bottom half of
statue that will
be welded
together.



Other damaged that will be repaired by LNS



Clamping the two pieces so that the alignment is perfect and tacked welded to assure proper fit.





Welding in process and showing the clamping system to keep statue in the correct alignment.

Welding process is almost complete and showing the back side of the statue.





Welding process
complete even down to
the rust finish to give it a
natural look.

