



Vintage 426 hemi block with matching numbers suffered freeze damage




Lower crack repair finished



Upper crack stitching in-process




Drain plug hole repair insert installed



Drain plug hole thread insert installation completed



Repair completed and pressure tested



Finished

