


# Cummins

## L-10

### Cracked injector hole repair





Alaa













L750-4

Tapcon<sup>®</sup>  
Tapping and Cutting  
Fluid for Cast Iron,  
Steel & Aluminum



Tapcon Inc.  
10001 - Turbines, CA 95380  
© 2015 • www.tapcon.com







































