

**Recent *LOCK-N-STITCH* repairs on large steel and cast iron parts**

Cracked water strainer casting for Hydro-electric plant in California



Over pressurization blew the side out of this casting.



Casting is prepared for high temperature brazing.



Metal stitching is performed in areas not accessible during brazing.  
Replacement not available. Cost for new casting \$55,000.00 USD.  
Cost for repair, \$10,000.00 Repair time, one week.